

Model: ADDA SAND L 120X120(A) Codes: 100309459 Water absorption: BIa - Porcelanico (E<=0.1%)



a DAPc<sup>®</sup> ación Ambiental de tor de Construcción

DIMENSIONAL FEATURES UNE-EN ISO 10545-2			
Thickness	8.5 MM	+/-5%*	
Width	1200 MM		
Length	1200 MM		
Length and width deviation	Below 0.15%	+/-0.3%*	
Side straightness deviation	Below 0.15%	+/-0.3%*	
Squareness deviation	Below 0.15%	+/-0.3%*	
Surface flatness deviation	Below 0.15%	+/-0.4%*	
*ISO-13006:2018 UNE-EN 14411:2016			

MECHANICAL FEATURES UNE-EN ISO 10545-4-6-7-11			
Breaking strength	2366 N	>1300N*	
Modulus of rupture	53 N/MM2	>=35N/mm2*	
Crazing resistance	Resists 3 cycles		
*ISO-13006:2018 UNE-EN 14411:2016			

## **HYGIENIC FEATURES** UNE-EN ISO 10545-13-14:1995

(resists attack). Minimum Class "B" for acids and bases

B Min.\*

3 Min.\*

Chemical resistance

Stain resistance

\*ISO-13006:2018 UNE-EN 14411:2016

## SCOPE OF USE

Class "A" for swimming pools and cleaning products

Class 5. Easy cleaning with water

Technical	code-1		
-----------	--------	--	--

	TI-SLIP VALUE
EN 1616	5: 2022 / ASTM C1028
Slip resistance (pendulum-wet) CL1	
Slip resistance (ramp) <r-9< td=""><th>TONO 8 / ID 2427*</th></r-9<>	TONO 8 / ID 2427*
Slip resistance (bare feet) B	tono 5 16801*

\*ISO-13006:2018 UNE-EN 14411:2016



Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.

## 100309459 ADDA SAND L

## PORCELANOSA Grupo

PACKING		
Sales units per box	1.440092 M2/BOX	
Sales units per pallet	60.483871 M2/PAL	
Sales units per unit	1.440092 M2/PIECE	



ACE

Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.